# Warn, when beyond the limit

positive current limit

soft start

value in parenthesis ---> Do not populate

value with asterix ---> value may have to be changed

	Lasertreiber (Limit)	0.1
		REV.:
TITLE		27.5.08
		DATE:
FILE: lasertreiber_3_limit.sch	-<(kmk)>-	
	DRAWN BY:	PAGE: 4/4